



-	+	AIS	D/N	C	NC	C1	T	T	NC1
1	2	3	4	5	6	7	8	9	10

## Shock detector CD 400-R





10	NC1	Alarm relay for magnet contact
9	T	Tamper
8	T	Tamper
7	C1	Alarm relay for magnet contact
6	NC	Alarm relay
5	C	Alarm relay
4	D/N	Day / Night control
3	AIS	First activated detector/ remote test
2	+	12 V
1	-	0 V



gap g=30 mm

## Shock detector CD 400-R



**Magnet should be placed axially, opposite to connectors 6-10.**

